



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	98	<b>Date:</b>	9/7/2004	<b>MeterBasin:</b>	01_WR11
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5714		Cross Country	Blvd
<b>Source Type:</b>	18= Other	<b>Location:</b>	5=Sidewalk
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	20
<b>Comments:</b>	crack in sidewalk		

## SMOKE TEST PHOTOS



**Photo No:** 1

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0001.JPG

**Image Status:** Image found and displayed.



**Photo No:** 2

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0002.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 98

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\98.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	98	<b>Date:</b>	9/7/2004	<b>MeterBasin:</b>	01_WR11
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5714		Cross Country	Blvd

<b>Source Type:</b>	18= Other	<b>Location:</b>	12=Alley	<b>Severity:</b>
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	0	

**Comments:** drainage cannot be determined

## SMOKE TEST PHOTOS



**Photo No:** 3

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0003.JPG

**Image Status:** Image found and displayed.



**Photo No:** 2

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0002.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 98

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\98.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	98	<b>Date:</b>	9/7/2004	<b>MeterBasin:</b>	01_WR11
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5701		Ridgedale	ROAD

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	150	

**Comments:** could be mainline stub

## SMOKE TEST PHOTOS



**Photo No:** 4

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0004.JPG

**Image Status:** Image found and displayed.



**Photo No:** 5

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0005.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 98

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\98.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	98	<b>Date:</b>	9/7/2004	<b>MeterBasin:</b>	01_WR11
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	4	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5701		Ridgedale	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
---------------------	--------------	------------------	--------------	------------------

<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	150
----------------	-----------	-----------------------	-----

**Comments:** could be mainline stub

## SMOKE TEST PHOTOS



**Photo No:** 5

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0005.JPG

**Image Status:** Image found and displayed.



**Photo No:** 6

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0006.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 98

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\98.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	99	<b>Date:</b>	9/7/2004	<b>MeterBasin:</b>	01_WR11
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5616		Cross Country	Blvd

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	5=Sidewalk	<b>Severity:</b>
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	0	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 7

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0007.JPG

**Image Status:** Image found and displayed.



**Photo No:** 8

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0008.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 99

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\99.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	99	<b>Date:</b>	9/7/2004	<b>MeterBasin:</b>	01_WR11
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
5616		Cross Country	Blvd

<b>Source Type:</b>	05= Downspout	<b>Location:</b>	8=Yard-Back	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	500	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 9

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0009.JPG

**Image Status:** Image found and displayed.



**Photo No:** 8

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0008.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 99

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\99.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	99	<b>Date:</b>	9/7/2004	<b>MeterBasin:</b>	01_WR11
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2304		Sulgrave	AVE

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	200	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 10

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0010.JPG

**Image Status:** Image found and displayed.



**Photo No:** 11

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0011.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 99

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\99.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	99	<b>Date:</b>	9/7/2004	<b>MeterBasin:</b>	01_WR11
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	4	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2306		Sulgrave	AVE

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	150	

**Comments:** holes in ground

## SMOKE TEST PHOTOS



**Photo No:** 12

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0012.JPG

**Image Status:** Image found and displayed.



**Photo No:** 13

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0013.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 99

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\99.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	99	<b>Date:</b>	9/7/2004	<b>MeterBasin:</b>	01_WR11
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	5	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2306		Sulgrave	AVE

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	50	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 13

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0013.JPG

**Image Status:** Image found and displayed.



**Photo No:** 14

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0014.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 99

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\99.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	99	<b>Date:</b>	9/7/2004	<b>MeterBasin:</b>	01_WR11
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	6	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2308		Sulgrave	AVE

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	5=Sidewalk	<b>Severity:</b>
---------------------	------------------	------------------	------------	------------------

<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	25
----------------	----------	-----------------------	----

**Comments:** hole in sidewalk

## SMOKE TEST PHOTOS



**Photo No:** 15

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0015.JPG

**Image Status:** Image found and displayed.



**Photo No:** 16

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0016.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

99

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\99.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	99	<b>Date:</b>	9/7/2004	<b>MeterBasin:</b>	01_WR11
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	Y
<b>Defect No:</b>	7	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>	
2310		Sulgrave	AVE	
<b>Source Type:</b>	14= Catch Basin	<b>Location:</b>	2=Paved Asphalt	<b>Severity:</b>
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	3300	
<b>Comments:</b>	corner of streets			

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 17

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0017.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

99

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\99.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY


Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	100	<b>Date:</b>	9/7/2004	<b>MeterBasin:</b>	01_WR11
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2212		Ken Oak	ROAD

<b>Source Type:</b>	05= Downspout	<b>Location:</b>	8=Yard-Back	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	250	
<b>Comments:</b>	Alley			

## SMOKE TEST PHOTOS




**Photo No:** 18

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0018.JPG

**Image Status:** Image found and displayed.



**Photo No:** 19

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0019.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 100

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\100.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland


<b>Unique Test ID</b>	100	<b>Date:</b>	9/7/2004	<b>MeterBasin:</b>	01_WR11
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2212		Ken Oak	ROAD

<b>Source Type:</b>	05= Downspout	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	100	

**Comments:** Alley

## SMOKE TEST PHOTOS



**Photo No:** 19

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0019.JPG

**Image Status:** Image found and displayed.



**Photo No:** 20

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0020.JPG

**Image Status:** Image found and displayed.



**Photo No:** 10

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\Retakes\UTID101-A2\_2005\_0523Image010.JPG


**Image Status:** Image found and displayed.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 100

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\100.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	100	<b>Date:</b>	9/7/2004	<b>MeterBasin:</b>	01_WR11
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2211		South	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	8=Yard-Back	<b>Severity:</b>
---------------------	--------------	------------------	-------------	------------------

<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	50
----------------	-----------	-----------------------	----

**Comments:** Alley

## SMOKE TEST PHOTOS



**Photo No:** 21

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0021.JPG

**Image Status:** Image found and displayed.



**Photo No:** 22

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0022.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 100

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\100.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	100	<b>Date:</b>	9/7/2004	<b>MeterBasin:</b>	01_WR11
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	4	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2207		South	ROAD

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	8=Yard-Back	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	50	

**Comments:** Alley/hole in ground

## SMOKE TEST PHOTOS



**Photo No:** 23

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0023.JPG

**Image Status:** Image found and displayed.




**Photo No:** 24

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0024.JPG

**Image Status:** Image found and displayed.



**Photo No:** 7

**Filename Path:**


X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\Retakes\UTID100-A4\2005\_0523Image007.JPG

**Image Status:** Image found and displayed.

## SMOKE TESTING OBSERVATION SUMMARY

# Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 100

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\100.tif

**Image Status:** Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	100	<b>Date:</b>	9/7/2004	<b>MeterBasin:</b>	01_WR11
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	5	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2214		Ken Oak	ROAD

<b>Source Type:</b>	08= Driveway Drain	<b>Location:</b>	4=Driveway	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	75	

**Comments:** Alley

## SMOKE TEST PHOTOS



**Photo No:** 25

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0025.JPG

**Image Status:** Image found and displayed.



**Photo No:** 26

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0026.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 100

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\100.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	100	<b>Date:</b>	9/7/2004	<b>MeterBasin:</b>	01_WR11
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	6	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2215		Ken Oak	ROAD

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	12=Alley	<b>Severity:</b>
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	100	

**Comments:** Alley/hole in ground

## SMOKE TEST PHOTOS



**Photo No:** 27

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0027.JPG

**Image Status:** Image found and displayed.



**Photo No:** 28

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0028.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 100

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\100.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	100	<b>Date:</b>	9/7/2004	<b>MeterBasin:</b>	
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	5501	<b>Street Prefix:</b>		<b>Street Name:</b>	Cross Country	<b>Street Type:</b>	Blvd
<b>Source Type:</b>	02= Service Line	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>			
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	50				
<b>Comments:</b>							

## SMOKE TEST PHOTOS



**Photo No:** 1

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0001.JPG

**Image Status:** Image found and displayed.



**Photo No:** 2

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0002.JPG

**Image Status:** Image found and displayed.

**Photo No:**


**Filename Path:**

**Image Status:** No image name specified.

## SMOKE TESTING OBSERVATION SUMMARY

# Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 100

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\100.tif

**Image Status:** Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland


<b>Unique Test ID</b>	100	<b>Date:</b>	9/7/2004	<b>MeterBasin:</b>	01_WR11
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	Y
<b>Defect No:</b>	2	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2216		Ken Oak	ROAD

<b>Source Type:</b>	14= Catch Basin	<b>Location:</b>	6=Curb	<b>Severity:</b>
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	2000	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 3

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0003.JPG

**Image Status:** Image found and displayed.



**Photo No:** 4

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0004.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH







# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	100	<b>Date:</b>	9/7/2004	<b>MeterBasin:</b>	01_WR11
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2215		Ken Oak	ROAD

<b>Source Type:</b>	18= Other	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	300	

**Comments:** Unkown source

## SMOKE TEST PHOTOS



**Photo No:** 5

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0005.JPG

**Image Status:** Image found and displayed.



**Photo No:** 6

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0006.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 100

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\100.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.